



Preliminary Information

PIT5888 Air Leveling Suspension Is Low After An Overnight Soak In Very Cold Temperatures

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Escalade Models	2021 - 2022	All	All	All	All
Chevrolet	Suburban	2021 - 2022	All	All	All	All
Chevrolet	Tahoe	2021 - 2022	All	All	All	All
GMC	Yukon Models	2021 - 2022	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	F47 - Air Leveling Suspension
Condition	Some customers may report that following and overnight cold soak, in temperatures below 0 Degs F (-15 Degs C), that the front air springs have leaked down resulting in severe suspension sag. A "Service Air Leveling System" message may be present on the driver information center (DIC) accompanied with DTC C118B and/or C118C. Note: This condition is not known to manifest itself in ambient temperatures warmer than 0 Degs F or -15 Degs C.
Cause	Unknown

Correction:

GM engineering is evaluating this concern and no repairs should be made at this time. Once more information is available, this PI will be updated.

Note: Do not drive the vehicle if the air springs have lost pressure as this can damage them to the point that they will require replacement.

Additional SI Keywords

level, spring

Version History

Version	1
Modified	01/28/2022 - Created on.



GENERAL MOTORS

© 2022 General Motors. All Rights Reserved.