

CAMPAIGN LAUNCH STATUS

H388 and N647 - SERVICE ACTIONS –UNABLE TO DISENGAGE AWD



CSP SERVICE ACTIONS– N647 and H388 UNABLE TO DISCONNECT AWD SYSTEM	
AFFECTED MODELS	21-22MY E-PACE, 21MY RR Evoque and Discovery Sport
VOLUME AFFECTED	Jaguar 1114 US 30 CAN Land Rover 9235 US 1030 CAN
ISSUE/REPAIR	Due to an issue with ABS module software, affected vehicles will not disconnect the rear wheels from the powertrain. The vehicle will remain in AWD and not declutch the wheels and self select 2-wheel drive mode. To correct this, affected vehicles will be updated with new All-Wheel Drive module software.
REPAIR TIME	0.20 hrs + Drive In/Out
CAMPAIGN REPAIR LAUNCH	January 24 th , 2022.
Notes	



PRINTED COPIES ARE UNCONTROLLED