



Bulletin No.: PIT5894

Published date: N/A

Preliminary Information

PIT5894 Tire Vibration Information

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 4500HD 5500HD 6500HD	2019 - 2022	All	All	All	All

Involved Region or Country	North America
Condition	Some customers may comment on a vibration while driving.
Cause	The cause of the condition may be that the wheel and tire assemblies require Road Force balance.

Correction:

Please open a **Tac** case and provide the following information.

- Check the valve stems on the dual rear wheel assemblies, are they pointing at each other (lined up)? should be 180 degrees from each other
- What wheels is the vehicle equipped with steel or Aluminum?
- What brand are the tires goodyear or Continental's?

Then follow bulletin [21-NA-270](#) for repair information.

Warranty Information

Version History

Version	1
Modified	02/08/2022 - Created on.



GENERAL MOTORS