	ch Tip T-TT-0681-22	February 21, 2022	
system (V35A)	V/DTCs for Turbocharger	Market USA	
Service Category Engine/Hybrid System Applicability	Section Engine Mechanical	l	
Tundra			
APPLICABLE VEHICLES			
2022	Tundra		
CONDITION Some 2022 MY Tundra vehicles, may experience a MIL ON condition with one or more of the following DTC(s): • DTC P024300 Turbocharger/Supercharger Wastegate Actuator "A" • DTC P024700 Turbocharger/Supercharger Wastegate Actuator "B" • DTC P25B372 Turbocharger/Supercharger Wastegate "A" Actuator Stuck Open • DTC P25B473 Turbocharger/Supercharger Wastegate "A" Actuator Stuck Closed • DTC P25B572 Turbocharger/Supercharger Wastegate "B" Actuator Stuck Open • DTC P25B673 Turbocharger/Supercharger Wastegate "B" Actuator Stuck Closed • DTC P25B673 Turbocharger/Supercharger Boost Sensor "A" Circuit Voltage Out of Range			
RECOMMENDATIONS			
	e repair manual process per DTC.		
NOTE:Turbocharger sub-assembl	ly is not a serviceable part.		

- Do not attempt to adjust or repair the turbocharger sub-assembly or its constituent components.
- If the turbocharger sub-assembly is found to be defective, it must be replaced.

LINK REFERENCES

- <u>V35A-FTS (INTAKE / EXHAUST): TURBOCHARGER: PRECAUTION; 2022 MY Tundra</u> [11/2021 - ??????]
- <u>V35A-FTS (INTAKE / EXHAUST): TURBOCHARGER: ON-VEHICLE INSPECTION; 2022 MY</u> Tundra [11/2021 - ??????]
- <u>V35A-FTS (INTAKE / EXHAUST): TURBOCHARGER: REMOVAL; 2022 MY Tundra [11/2021 ??????]</u>
- V35A-FTS (INTAKE / EXHAUST): TURBOCHARGER: INSPECTION; 2022 MY Tundra [11/2021 - ???????]
- V35A-FTS (INTAKE / EXHAUST): TURBOCHARGER: INSTALLATION; 2022 MY Tundra

ΦΤΟΥΟΤΑ	Tech Tip T-TT-0681-22	February 21, 2022
system (V35A)	IL ON W/DTCs for Turbocharger	Market USA
Applicability		
[11/2021 - ?????	???]	

Ver. 4.0 01/01/2022 T