## $\mathbf{V} \mathbf{O} \mathbf{L} \mathbf{V} \mathbf{O}$

# TRUCKS DEALER BULLETIN

To: General Managers, Service Managers, Service Technicians, Warranty Managers

From: Volvo Trucks – Service

**Date:** March 31, 2022

Subject: Service Literature Published and Released in March, 2022

Bulletin: SLV22-003

The following summarizes the service literature that has been published and/or revised for the month.

#### **SERVICE NEWS**

BULLETIN #	TITLE	COMMENTS
SNV22-003	When and How to Engage Dealer Technical Support	New

#### **TOOL BULLETINS**

BULLETIN #	TITLE	COMMENTS
	None Issued	

#### **TECHNICAL SERVICE BULLETINS**

BULLETIN#	TITLE	COMMENTS
V-821-001	Hood Cable Breaking or Binding	New

#### **SERVICE PROGRAMS**

BULLETIN #	TITLE	COMMENTS
	None Issued	

#### **RECALLS**

BULLETIN #	TITLE	COMMENTS
SRA-V22-01	Safety Recall Alert RVXX2201, Volvo VN Sleeper Cabinets	New
C6640	RVXX2201, Volvo VN Sleeper Cabinets	New

<sup>© 2022</sup> Volvo Group North America, LLC. CONFIDENTIAL - For limited distribution only to circulation list above. This bulletin, and any information herein, is subject to change by Company without notice. For the most current and accurate information, always refer to Trucks Dealer Portal for the electronic version of this document.

### V O L V O

# TRUCKS DEALER BULLETIN

#### **CASE BASED REASONING (CBR)**

#### **NEW SOLUTIONS**

SOLUTION #	TITLE	
CBR-2162	CAN Reader Not Registering Vehicle Speed After TECU Software Update	
CBR-2165 DEF Pump Troubleshooting Guide - US10+OBD13 And Newer Emissions		

#### **UPDATED SOLUTIONS**

SOLUTION	TITLE	COMMENTS
CBR-291	Volvo Chassis -Pressure Protection Manifold Plugs - New Brass Plugs For Noregon Pressure Protection Manifold (PPM)	Added TPI 563-014 Ref