

Subject: Engineering Information - Popping and/or Clunking Type Noise Heard During Hard Turns, Steep Driveway Entries/Exits and/or Going Over Speed Bumps, Creaking Type Noise While Turning Wheel Left and/or Right, Clicking Type Noise Heard On Slow Sharp Turns

This PI has been revised to end the need for information from the field. Please discard PIE0679.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	Escalade Models	2021	2022	-	-	-	-
Chevrolet	Silverado 1500	2019	2021				
	Silverado 1500 LTD (RPO J21, 12th VIN Digit = 4 or less)	2022	2022				
	Suburban	2021					
	Tahoe						
GMC	Sierra 1500	2019	2021				
	Sierra 1500 Limited (RPO J21, 12th VIN Digit = 4 or less)	2022	2022				
	Yukon Models	2021					

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released February 28, 2022 Revised March 31, 2022 – Ended the need for further information from the field.