

TECHNICAL TOPICS

BODY/CHASSIS



<p>Power Steering Assistance Reduced Message Displayed</p>	<p>20-22MY Defender 21-22MY Discovery</p>
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"> A customer may report that “Power Steering Reduced” message displays on the message center on start-up with a reduction in steering assist. <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> This may be caused by voltage dipping to low to the Power Steering Control Module (PSCM) during start-up. <p><u>Status:</u></p> <ul style="list-style-type: none"> Revised PSCM software has been created to address this concern and was released on PATHFINDER version 367. SSM75704 has been published to address this concern. 	<p>PATHFINDER</p> <p>JOIN THE JOURNEY</p> 

