

TECHNICAL TOPICS

BODY/CHASSIS



2nd Row Seat Recline Motors Available as Lower Level Assembly

17MY-Onwards Discovery, Range Rover, RR Sport

Customer Voice:

- A customer may report that the 2nd row seat does not recline.

Technical Description:

- This may be caused by a seat recline motor malfunction.

Status:

- The 2nd row seat recline motors have now been released as a lower level service part.
- Please refer to the Electronic Parts Catalog (EPC) with the VIN for the correct lower level assembly part number should diagnosis of a customer concern identify a recline motor failure.
- The replacement procedure has been added to the Workshop Manual, section 501-10: Seating > Removal and Installation > Rear Seat Recline Motor.

