

VIN:



TIFFIN

MOTORHOMES

105 2nd Street NW
Red Bay, Alabama 35582

**Daimler Trucks North America NHTSA Recall # 21V-00H
Freightliner Campaign # FL917
FCCC Motorhome Chassis Rear PDM's**

March 31, 2022

Dear Tiffin Motorhome Customer,

Please see the letter printed on the reverse from Daimler Trucks North America on behalf of Freightliner Custom Chassis Corporation, about a safety recall Freightliner has released that is applicable for the VIN listed above. This is the second of 2 letters you will receive regarding this subject. This letter informs you that the remedy for this recall has been released. If you have questions about this recall, please contact the Freightliner's Warranty Campaigns Department at (800) 547-0712, 7:00 a.m. to 4:00 p.m. Pacific Time, Monday through Friday, or by e-mail at DTNA.Warranty.Campaigns@Daimler.com.

Thank you for your attention to this matter,

Tiffin Motorhomes Recall Department

**Daimler Trucks
North America LLC**

Daimler Trucks North America LLC
Warranty Campaigns Department
P.O. Box 4090
Portland, OR 97208-4090
800.547.0712 Phone

**March 2022
FL917A
NHTSA #21V-00H**

IMPORTANT SAFETY RECALL
See enclosed VIN list

Subject: FCCC Chassis Rear PDMs

This notice is sent to you in accordance with the requirements of the *National Traffic and Motor Vehicle Safety Act*.

Daimler Trucks North America LLC (DTNA), on behalf of its wholly owned subsidiary, Freightliner Custom Chassis Corporation, has decided that a defect which relates to motor vehicle safety exists on specific Model Year 2016–2023 Freightliner Custom Chassis X-Line chassis manufactured November 23, 2015, through December 7, 2021, and equipped with a certain Power Distribution Module (PDM).

FCCC X-Line chassis, equipped with a certain rear mounted Power Distribution Module (PDM), may experience cracked internal solder joints, which after a period of vehicle use may lead to intermittent open circuits, in which the rear marker lights, brake lights, or left turn signal lights may not function. Brake lights that do not function correctly may not notify motorists of a braking event, which may lead to an increase risk of crash.

A secondary fused harness will be added which bypasses the affected suspect portion of the PDM. Repairs will be performed by Daimler Trucks North America authorized service facilities.

This is the second notice regarding this recall. The final recall repair is now available and parts have been secured. Please contact an authorized Daimler Trucks North America dealer to arrange to have the Recall performed and to ensure that parts are available at the dealership. To locate an authorized dealer, search online at Daimler-TrucksNorthAmerica.com/Contact-us. Scroll down to "Locate a Dealer" and select the appropriate brand. The Recall will take approximately one hour and will be performed at no charge to you. You may also confirm your vehicle's involvement in this recall at this URL: <https://dtna-dlinfo.prd.freightliner.com:48518/VinLookup/vin-module/getVinLookupPage>.

You may be liable for any progressive damage that results from your failure to complete the Recall within a reasonable time after receiving notification.

If you do not own the vehicle that corresponds to the identification number(s) which appears on the Recall Notification, please return the notification to the Warranty Campaigns Department with any information you can furnish that will assist us in locating the present owner. If you have leased this vehicle, Federal law requires that you forward this notice to the lessee within 10 days. If you are a subsequent stage manufacturer, Federal law requires that you forward this notice to your distributors and retail outlets within five working days. If you have paid to have this recall condition corrected prior to this notice, you may be eligible to receive reimbursement. Please see the reverse side of this notice for details.

If you have questions about this Recall, please contact the Warranty Campaigns Department at (800) 547-0712, 7:00 a.m. to 4:00 p.m. Pacific Time, Monday through Friday, e-mail address DTNA.Warranty.Campaigns@Daimlertruck.com. For other concerns, you may contact the Customer Assistance Center at (800) 385-4357. If you are not able to have the defect remedied without charge and within a reasonable time, you may wish to submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE, Washington, DC 20590; or call the Vehicle Safety Hotline at (888) 327-4236 (TTY: 800-424-9153); or go to <http://www.safercar.gov>.

We regret any inconvenience this action may cause but feel certain you understand our interest in motor vehicle safety.

WARRANTY CAMPAIGNS DEPARTMENT
Enclosure

Reimbursement to Customers for Repairs Performed Prior to Recall

If you have already **paid** to have this recall condition corrected you may be eligible to receive reimbursement.

Requests for reimbursement may include parts and labor. Reimbursement may be limited to the amount the repair would have cost if completed by an authorized Daimler Trucks North America LLC dealer. The following documentation must be presented to your dealer for consideration for reimbursement.

Please provide original or clear copies of all receipts, invoices, and repair orders that show:

- The name and address of the person who paid for the repair.
- The Vehicle Identification Number (VIN) of the vehicle that was repaired.
- What problem occurred, what repair was done, when the repair was done.
- Who repaired the vehicle.
- The total cost of the repair expense that is being claimed.
- Proof of payment for the repair (such as the front and back of a cancelled check or a credit card receipt).

Reimbursement will be made by check from your Daimler Trucks North America LLC dealer.

Please speak with your Daimler Trucks North America LLC authorized dealer concerning this matter