



Preliminary Information

PIT5812C Grind Noise From Brakes

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Equinox	2021 - 2022	All	All	All	All
GMC	Terrain	2021 - 2022	All	All	All	All

Involved Region or Country:	North America
Condition:	Grinding noise on brake apply cold that dissipates after a few stops.
Cause:	New no copper pad composition.

Engineering is investigating this concern and working towards a resolution. Replacing pads will not eliminate this concern for the long term. Deglazing the pads and rotors does help the concern in the short term. This PI will be removed and a bulletin released when the field fix is available.

Version History

Version	4
Modified	02/02/2021 - Created on. 05/10/2021 - Revised to add models. 06/30/2021 - Removed Colorado and Canyon models due to the release of 21-NA-142 03/15/2022 - Added 2022 model year.



GENERAL MOTORS