



Technical Service Bulletin

90 Instrument cluster: software version information screen pops up in the center display

90 22 59 2063038/2 April 16, 2022. Supersedes Technical Service Bulletin Group 90 number 21-99 dated April 26, 2021, for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
TT, TTS, and TT Roadster	2016 – 2023	All	Audi Virtual Cockpit
A3, and S3	2016 – 2020 2022 – 2023		
A3 Cabriolet	2016 – 2019		
A3 Sportback e-tron	2016 – 2018		
A4 allroad, and A4	2017 – 2023		
RS 3	2017 – 2020 2023		
R8, and R8 Spyder	2017 – 2018 2020 – 2023		
S4, A5, S5, A5 Cabriolet, S5 Cabriolet, A5 Sportback, S5 Sportback, Q5, SQ5, and Q7	2018 – 2023		
TT RS	2018 – 2022		
Q8	2019 – 2023		
RS 5 Sportback	2019 2021 – 2023		
Q5 e quattro, SQ7, SQ8, RS Q8	2020 – 2023		

Condition

REVISION HISTORY		
Revision	Date	Purpose



Technical Service Bulletin

2	-	Revised header (Added MY 2023)
1	04/26/2021	Initial publication

Customer states:

After pressing the trip odometer reset button (0.0 button), the content in Figure 1 is displayed in the center display area of the instrument cluster.



Figure 1. Version information screen.

Technical Background

Since open-source software is used in the Audi virtual cockpit, the manufacturer is obliged to display the relevant information and license conditions in the Audi virtual cockpit on demand.

This version information screen is displayed after pressing the trip odometer reset button twice within five seconds after turning on the ignition. This is a legally required display feature and not a quality defect of the vehicle.

Production Solution

Not applicable.



Technical Service Bulletin

Service

Please inform the customer that the reset button of the trip odometer should only be pressed once within five seconds after switching on the ignition. Otherwise, the software information screen will be displayed.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (2063038) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.