

Technical product information

Topic	ACC Control units (J428 and J850) - Replacement guidelines
Market area	Russische Föderation (5RU),Australia E04 Bentley rest Asia and Australia (6E04),China 796 VW Import Comp. Ltd (Vico), Beijing (6796),Germany E02 Bentley rest Europe (6E02),Japan E03 Bentley Japan (6E03),Korea, (South) E08 Bentley South Korea (6E08),United Arab Emirates E06 Bentley Middle East and Africa (6E06),United Kingdom E01 Bentley UK (6E01),United States E05 Bentley USA and rest America (6E05)
Brand	Bentley
Transaction No.	2066708/1
Level	EH
Status	Approval
Release date	

New customer code

Object of complaint	Complaint type	Position
driver assist systems, convenience features -> cruise control/ACC -> adaptive cruise control (ACC)	functionality -> without function / defect	
vehicle service -> vehicle diagnosis -> guided fault finding	control units, services -> with event log entry	
driver assist systems, convenience features -> cruise control/ACC -> adaptive cruise control (ACC)	functionality -> defective function sequence	

Vehicle data

Bentayga 22 Model year

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
4V1*	2022	E		*	*	*

Equipment combinations

PR numbers
with 8T3
or with 8T8

Documents

Document name
master.xml

Customer statement / workshop findings

In the event that the Master and or Slave ACC Control units (J428 and J850) require replacement, the operative should refer to the Measure section of this TPI

Technical background

Refer to the Measure section of this TPI

Production change

-

Measure

Internal changes of the Master and or Slave ACC Control units (J428 and J850) have been made by the supplier

Therefore

In the event that a 'C' level part is fitted and requires replacement, the control units must be replaced in pairs with the D suffix parts listed below:

Master ACC Control unit - 36A 907 561C to 36A 907 561D

Slave ACC Control unit - 36A 907 541C to 36A 907 541D

▪

When replacing the Master and or Slave ACC Control units (J428 and J850) the operative should refer to the instructions within Rep.Gr 44

Parts information

In the event that a 'C' level part is fitted and requires replacement, the control units must be replaced in pairs with the D suffix parts listed below:

Master ACC Control unit - 36A 907 561C to 36A 907 561D

Slave ACC Control unit - 36A 907 541C to 36A 907 541D