

32-021 Cummins X15 MY2022 Auto Start Inoperative after Cummins Engine Software Update

4/18/2022

[Edit](#) [Clone](#)

32-021

Section

Starter, Battery - 32

Subject

Cummins X15 MY2022 Auto Start Inoperative after Cummins Engine Software Update

Whats New Abstract

Model Year 2022 chassis with Cummins X15 engines may have inoperative auto-start systems due to a Cummins software update. Refer to Cummins bulletin TSB210135.

Condition

Engine Auto Start/Stop system does not operate properly after Installing Cummins Engine Software KW10119.04

Chassis Affected

Model Year 2022 T680, T680 NextGen, T880, W990, C500, T800, W900 Chassis equipped with Cummins X15 CM2450 X124B or X15 CM2450 X134B engine and Auto Start/Stop system.

Action

Information Only

Refer to Cummins TSB210135 for repair procedures

Procedure

Please follow your dealership's safety procedures and precautions to ensure the vehicle can be safely repaired and maintained.

Refer to Cummins TSB210135 to address this concern.

Authored by: JB3