

VOLVO

TRUCKS DEALER BULLETIN

To: General Managers, Service Managers, Service Technicians, Warranty Managers
From: Volvo Trucks – Service
Date: April 30, 2022
Subject: Service Literature Published and Released in April, 2022
Bulletin: SLV22-004

The following summarizes the service literature that has been published and/or revised for the month.

SERVICE NEWS

BULLETIN #	TITLE	COMMENTS
	None Issued	

TOOL BULLETINS

BULLETIN #	TITLE	COMMENTS
STB22-002V	Cam Lobe Measuring Tool	New

TECHNICAL SERVICE BULLETINS

BULLETIN #	TITLE	COMMENTS
	None Issued	

SERVICE PROGRAMS

BULLETIN #	TITLE	COMMENTS
S7631	Proprietary Steerable Axle Hubcap Replacement	New
S7639	Proprietary Fixed Axle Hubcap Replacement	New

RECALLS

BULLETIN #	TITLE	COMMENTS
	None Issued	

V O L V O

TRUCKS DEALER BULLETIN

CASE BASED REASONING (CBR)

NEW SOLUTIONS

SOLUTION #	TITLE
CBR-2171	Temperature Sensor Troubleshooting Guide - US10+OBD13 And Newer

UPDATED SOLUTIONS

SOLUTION	TITLE	COMMENTS
CBR-585	Volvo Delphi Radio Theftlock Code Generator	Updated tags for improved searchability.
CBR-586	Volvo SNV14-023 Vehicle Modifications Or Upgrades That Require Programming	Updated tags for improved searchability.
CBR-588	Volvo SNV 14-033 Design and Function of Warm Hold Feature	Updated tags for improved searchability.
CBR-914	Volvo Chassis - D12C, D12D, D11F, D13F, D16D, D16F Engines - Copper Injector Sleeves, Replacement Procedure And Information (Flat Tip Injectors) - US04 To US07 Emissions	Withdrawn - Information in solution is no longer valid. Updated information can now be found in Impact.
CBR-589	Engine Control Module (EMS) Software Information - Improvement List, August 2021 - US17+OBD2019 Emissions	Updated tags for improved searchability.
CBR-590	Volvo Chassis - Injector Trim Code Calibration (Programming) with Premium Tech Tool (PTT) – US10+OBD13 And Newer (Includes Common Rail Fuel System) Emissions, Common Model Year 2014 And Newer	Updated tags for improved searchability.
CBR-594	Volvo Chassis - Vehicles Equipped With An Automated Manual Transmission Model F (AMT-F, I-Shift), Premium Tech Tool (PTT) Gearbox Calibration Failure; Gearbox Calibration Operation Stops And Fails At 33% When Run With Transmission Removed	Withdrawn - Information is no longer valid.
CBR-596	Volvo Chassis With Cummins Engine Odometer Programming Option Not Showing In Tech Tool After The Cluster (MID140) Has Been Programmed	Updated tags for improved searchability
CBR-597	Data Link Diagnostics - Control Box 88890276, Information	Updated tags for improved searchability
CBR-598	Volvo Chassis - VAH Models - SNV14-011 Autohauler Unique Cab Parts Identification And Ordering Information; Special Parts For Auto Hauler Vehicles - Model Years 2007 To 2017	Updated tags for improved searchability
CBR-2018	Diagnostic Trouble Code P200200 - Diagnostic Information; US14+OBD16 And Newer Emissions	Updated tags for improved searchability
CBR-66	Volvo Chassis - LED Headlights Conversion Programming Procedure - Model VNL	Updated tags for improved searchability
CBR-600	Volvo SNV15-002 Meritor - WABCO ECAD - Electronically Controlled Air Dryer, Connector Issue	Updated tags for improved searchability
CBR-601	Volvo Chassis - Windshield Wiper Function Inoperative In Intermittent Mode ONLY	Updated tags for improved searchability