

Rear Toe Actuator Warning Lights with DTC C1600-94

AFFECTED VEHICLES

Year	Model	Trim Level
2019–20	TLX	FWD

Clients are experiencing multiple warning lights coming on with DTC C1600-94 (Precision All Wheel Steer System Unexpected Operation). You need to do an all DTC check. If you can duplicate and related codes are present, follow the appropriate troubleshooting. If you cannot duplicate the contention after clearing the DTC then follow up with the client and document the driving conditions needed to replicate the complaint.

To better understand your client's complaint at the time when the DTC warning lights came on, please ask if they noticed the following:

- Limp mode (Yes/No):
- Road conditions (Dry/Wet/Snow/Gravel/Grass):
- Throttle input (Accel/Decel/Cruising):
- Driving conditions (Straight ahead or obstacle avoidance maneuver e.g., Pothole/Ball/Animal):
- If turning, steering wheel input (e.g. 9 o'Clock, 1 o'Clock):
- Last alignment (Date):
- And Before/After alignment results:

Please provide VIN, mileage and customer feedback to tis@ahm.honda.com.