

Subject: Engineering Information - Power Floor Console Armrest will not Lock in Place and/or Console Lid Slides Back and Forth Freely

This PI has been revised to end the need for information from the field. Please discard PIE0677A.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Suburban	2021	2022	—	—	—	—
	Tahoe						
GMC	Yukon Models						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	3
Modified	Released January 28, 2022 Revised February 02, 2022 – Revised to update the model years. Revised April 27, 2022 – Ended the need for further information from the field.