TECHNICAL TOPICS

Powertrain





Customer Voice:


- Customer concern will be a failure to restart after an Eco-stop. This may be interpreted as a stall, but the ignition will also turn off.

Technical Description:
- DTC code that will be stored will be P162F.

Status:

- PCM software has been created to resolve the issue. TOPIx Cloud(OTX TBC)

Refer to SSM 75712



20-22MY Defender







