


# TECHNICAL TOPICS

## BODY/CHASSIS



| Deployable Sidestep Erratic Operation   | 22MY New Range Rover (L460)   |
|---|---|
| <p><u>Customer Voice:</u></p> <ul style="list-style-type: none"><li>- A customer may report that the deployable sidesteps are operating erratically.</li></ul> <p><u>Technical Description:</u></p> <ul style="list-style-type: none"><li>- The accessory fit deployable sidesteps may operate erratically or intermittently on one or doth sides. This may be a result of a fixing that has become loose.</li></ul> <p><u>Status:</u></p> <ul style="list-style-type: none"><li>- Should a customer express a concern please refer to SSM 75721 for a list of related DTC's and repair procedures.</li></ul> |  <p>E304247</p> |

