

TECHNICAL TOPICS

BODY/CHASSIS



2 nd Row Seat Recline Motors Available as Lower Level Assembly	17MY-Onwards Discovery, Range Rover, RR Sport
<p>Customer Voice:</p> <ul style="list-style-type: none"> A customer may report that the 2nd row seat does not recline. <p>Technical Description:</p> <ul style="list-style-type: none"> This may be caused by a seat recline motor malfunction. <p>Status:</p> <ul style="list-style-type: none"> The 2nd row seat recline motors have now been released as a lower level service part. Please refer to the Electronic Parts Catalog (EPC) with the VIN for the correct lower level assembly part number should diagnosis of a customer concern identify a recline motor failure. The replacement procedure has been added to the Workshop Manual, section 501-10: Seating > Removal and Installation > Rear Seat Recline Motor. 	<p>5011030 06-2021 LK 00237890-07</p> <p>© Copyright, 2016 - 2021, Jaguar Land Rover Limited.</p>

