## **TECHNICAL TOPICS BODY/CHASSIS**





## 17MY-Onwards Range Rover, RR Sport, XF, F-Seat Cushion Pan Service Kit Available as Lower Level Assembly TYPE 15-19MY RR Evoque, 11-20MY XJ **Customer Voice:** A customer may report a rattle tyle noise from the front seat base area.

## Technical Description:

This may be caused by a seat pan bracket.

## Status:

- A front seat pan service kit has now been released as a lower level service part to allow a repair to be done in the vehicle without separating the seat cushion from the seat squab.
- Please refer to the Electronic Parts Catalog (EPC) with the VIN for the correct lower level assembly part number should diagnosis of a customer concern identify a seat pan bracket concern.
- The replacement procedure has been added to the Workshop Manual, section 501-10: Seating > General Procedures > Front Row Seat Pan Bracket.









