

Reference	SSM75712
Models	Defender / L663 Discovery / L462
Title	3.0L I6 Petrol Intermittent Engine Non Start After An Eco Stop Start Event
Category	Engine
Last modified	27-Apr-2022 00:00:00
Symptom	499000 Basic Engine

Content

Issue: JLR is investigating customers reporting intermittent non start after an eco-stop start event for L663 and L462 3.0L I6 Petrol derivatives only.

Cause: Currently under analysis.

Action: If a customer reports the concern above, please carry out a software update to the Powertrain Control Module using Pathfinder with P368 onwards.

1. Connect the Jaguar Land Rover (JLR) approved battery support unit.
2. Connect the JLR approved diagnostic equipment to the vehicle and begin a new session.
3. Follow the JLR approved diagnostic equipment prompts.
4. Select 'ECU Diagnostics'.
5. Select 'Powertrain Control Module'.
6. Select 'Update ECU'.
7. Follow all on screen prompts to complete the task.
8. When all tasks are complete exit the session.
9. Disconnect the JLR approved diagnostic equipment and battery support unit'.

anBhdHRlcnM7MjAyMi0wNS0wM1QxMzozOTowNC4wNTVaOzEzNi4yMjYyNDguMTI1Ow==