

Reference	SSM75728
Models	E-PACE / X540 F-PACE / X761 F-TYPE / X152 I-PACE / X590 XE / X760 XF / X260
Title	21 MY Onwards PIVI PRO USB Inoperative Cross Car Line
Category	Electrical
Last modified	05-Apr-2022 00:00:00
Symptom	203000 Basic Electrical
Content	<p><u>Issue</u> USB stick not recognised when inserted into the Front Portable Media Interface Panel (FPMIP). This can occur in the following scenarios:</p> <ol style="list-style-type: none">1. Installing maps at PDI.2. Updating the ICCM/IGM via service tools.3. Media playback from a source connected via USB. <p><u>Cause</u> Under investigation.</p> <p><u>Action</u> Please Do NOT attempt any repairs or reset the system until advised, if this issue is observed, raise a TA for further assistance for the attention of (EES_200) and await further instructions.</p> <p><small>anBhdHfRlcnM7MjAyMj0wNS0wM1QzMTo1MDowOS45MTdsOzEzNi4yMjYyNDguMT11Ow==</small></p>