

# GUARDDOG CONNECT



**DTC:** P0117-00

**Bulletin:** GDC22-191

**Date:** April 01, 2022

**Description:** See below for fault code description(s)

**Applies to:** US ARMY VEHICLES

## General Information

These repair instructions are intended to address the following fault(s):

DTC	Description	Possible Cause	Possible (Observable) Symptoms
P0117-00	IDTC_COOLTEMP_S CL – Voltage Below Normal or Shorted Low	<ul style="list-style-type: none"><li>• Connector</li><li>• Wiring harness</li><li>• Engine coolant temperature sensor</li><li>• Engine Control Module</li></ul>	<ul style="list-style-type: none"><li>• High fuel consumption</li><li>• The engine coolant temperature (ECT) gauge shows 0</li><li>• Engine fan constantly engaged</li><li>• Less powerful engine since the fan takes power from the engine</li></ul>

## Required Parts

Part Number	Description	Quantity
N/A	PTT, VOCOMII	1

## Repair Instructions

Please reference the following file(s):

- IETM, WP File Name: **T00811**
- IETM, WP Number: **177**

## Additional Resources

- For support with a warrantable fault/fault code, please submit an SF368 Product Quality Deficiency Report (PQDR) in the Product Data Reporting & Evaluation Program (PDERP) at <https://www.pdrep.csd.disa.mil/> and CC or forward the PDREP generated .pdf copy of the SF368 to appropriate Mack Defense Warranty Managers:

Margaret Baranowski  
(484)-743-7127  
[margaret.baranowski@mackdefense.com](mailto:margaret.baranowski@mackdefense.com)

William Beard  
(610)-573-4954  
[william.beard@mackdefense.com](mailto:william.beard@mackdefense.com)

**DTC:** P0117-00

**Bulletin:** GDC22-191

**Date:** April 01, 2022

- For assistance with normal service or technical related questions, please contact our Contractor Logistics Support (CLS) provider POCs:

Rich Rader  
(910) 797-0903  
[richard.rader@mantech.com](mailto:richard.rader@mantech.com)

Gil Esplana  
(254) 404-5409  
[gil.esplana@mantech.com](mailto:gil.esplana@mantech.com)