# **GUARDDOG CONNECT**



DTC: P02CD-00 Bulletin: GDC22-161

Date: April 01, 2022

**Description:** See below for fault code description(s)

Applies to: US ARMY VEHICLES

#### **General Information**

These repair instructions are intended to address the following fault(s):

DTC	Description	Possible Cause	Possible (Observable) Symptoms
P02CD-00	IDTC_INJECTOR1_O OCPOS – High-Least Severe (1)	<ul> <li>Solenoid valve,Power Take Off (PTO)</li> <li>Valves and rocker arms</li> <li>Camshaft</li> <li>Excessive wear or damage to cylinder liners, piston, or piston rings</li> <li>Inlet valves</li> <li>Exhaust valves</li> <li>Injector</li> </ul>	Uneven torque

## **Required Parts**

Part Number	Description	Quantity
N/A	PTT, VOCOMII	1

#### **Repair Instructions**

Please reference the following file(s):

IETM, WP File Name: T00820IETM, WP Number: 194

### **Additional Resources**

 For support with a warrantable fault/fault code, please submit an SF368 Product Quality Deficiency Report (PQDR) in the Product Data Reporting & Evaluation Program (PDERP) at <a href="https://www.pdrep.csd.disa.mil/">https://www.pdrep.csd.disa.mil/</a> and CC or forward the PDREP generated .pdf copy of the SF368 to appropriate Mack Defense Warranty Managers:

Margaret Baranowski (484)-743-7127 margaret.baranowski@mackdefense.com

William Beard (610)-573-4954 william.beard@mackdefense.com

# **GUARDDOG CONNECT**



DTC: P02CD-00 Bulletin: GDC22-161

**Date:** April 01, 2022

• For assistance with normal service or technical related questions, please contact our Contractor Logistics Support (CLS) provider POCs:

Rich Rader (910) 797-0903 richard.rader@mantech.com

Gil Esplana (254) 404-5409 gil.esplana@mantech.com