# **GUARDDOG CONNECT**



DTC: P02D5-00

Bulletin: GDC22-182 Date: April 01, 2022

**Description:** See below for fault code description(s)

Applies to: US ARMY VEHICLES

#### General Information

These repair instructions are intended to address the following fault(s):

DTC	Description	Possible Cause	Possible (Observable) Symptoms
P02D5-00	IDTC_INJECTOR5_O OCPOS – High-Least Severe (1)	<ul> <li>Solenoid valve,Power Take Off (PTO)</li> <li>Valves and rocker arms</li> <li>Camshaft</li> <li>Excessive wear or damage to cylinder liners, piston, or piston rings</li> <li>Inlet valves</li> <li>Exhaust valves</li> <li>Injector</li> </ul>	Uneven torque

### **Required Parts**

Part Number	Description	Quantity
N/A	PTT, VOCOMII	1

#### **Repair Instructions**

Please reference the following file(s):

- IETM, WP File Name: T00832
- IETM, WP Number: 198

#### Additional Resources

 For support with a warrantable fault/fault code, please submit an SF368 Product Quality Deficiency Report (PQDR) in the Product Data Reporting & Evaluation Program (PDERP) at <a href="https://www.pdrep.csd.disa.mil/">https://www.pdrep.csd.disa.mil/</a> and CC or forward the PDREP generated .pdf copy of the SF368 to appropriate Mack Defense Warranty Managers:

Margaret Baranowski (484)-743-7127 margaret.baranowski@mackdefense.com

William Beard (610)-573-4954 william.beard@mackdefense.com

## **GUARDDOG CONNECT**



DTC: P02D5-00

 Bulletin:
 GDC22-182

 Date:
 April 01, 2022

• For assistance with normal service or technical related questions, please contact our Contractor Logistics Support (CLS) provider POCs:

Rich Rader (910) 797-0903 richard.rader@mantech.com

Gil Esplana (254) 404-5409 gil.esplana@mantech.com