

**February 26, 2016**

03230 Version 1

## Product Update: 2016 Civic Monroney Label (Except Hawaii)

### AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2016	Civic	ALL	Check the iN VIN status for eligibility

### BACKGROUND

On the Monroney label, the bumper compliance impact speed listed was carried over from 2015 models and is incorrect for 2016 vehicles.

Do an iN VIN status inquiry to make sure the vehicle is shown as eligible.

Vehicles affected by this campaign may be in your new vehicle inventory. Repair these vehicles before they are sold. No action is needed on vehicles that have been sold.

### CORRECTIVE ACTION

Attach the Monroney update label to the window area next to the Monroney label.

### PARTS INFORMATION

Part Name	Part Number	Quantity
Monroney Update Label (Except New York)	Y1071	1
Monroney Update Label (For vehicles located in New York)	Y1072	1

Extra labels are not available through the normal parts ordering process. Contact Helm Inc. at 800-782-4356, and use the applicable reorder number.

### WARRANTY CLAIM INFORMATION

NOTE: Do not enter a part number in the warranty claim because the warranty claim will reject if you try to enter the Helm part number.

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
8290A2	Attach the Monroney update label.	0.2 hr	6AG00	JX600	16-019A	73450-TBA-A00

**CUSTOMER INFORMATION:** The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.

## REPAIR PROCEDURE

Make sure the inside window area is clean, dry, and at room temperature. Attach the applicable Monroney update label in the position shown.

### NOTE:

- If necessary, bring the vehicle inside to warm up to room temperature; otherwise the label may not stick to the glass.
- Vehicles located in New York use a label that is different from the other states.



END