


 HYUNDAI Technical Service Bulletin	GROUP ENGINE	NUMBER 22-EM-002H-1
	DATE APRIL 2022	MODEL(S) APPLICABLE VEHICLES BELOW
SUBJECT: ENGINE WARRANTY EXTENSION (TXXC)		

This TSB supersedes TSB 22-EM-002H to update the applicable vehicles to include the Sonata, Santa Fe Sport, Santa Fe, and Tucson models.

Description: The warranty coverage for engine long block repair or replacement regarding engine damage or malfunction from connecting rod bearing wear has been extended to 10 years or 120,000 miles from the date of original retail delivery or date of first use, whichever occurs first. Warranty coverage is valid for original and subsequent owners.



NOTICE

A Warranty Prior Approval (PA) must be submitted on all applicable vehicles that exhibit the conditions above within the extended warranty period. PA will provide detailed confirmation of engine approval or denial based on all available case details and applicability of any related terms.

Please refer to TSB #21-EM-004H-1 (or latest version) for the service procedure for engine connecting rod bearing clearance testing.

Please refer to TSB # 22-01-034H (or latest version) for applicable part numbers and labor ops.

Applicable Vehicles:

- Certain 2011-2014 MY Sonata (YF) vehicles with Theta II 2.0L Turbo and 2.4L GDI engines
- Certain 2015-2019 MY Sonata (LF) vehicles with Theta II 2.0L Turbo and 2.4L GDI engines
- Certain 2013-2018 MY Santa Fe Sport (AN) vehicles with Theta II 2.0L Turbo and 2.4L GDI engines
- Certain 2019 MY Santa Fe (TM) vehicles with Theta II 2.0L Turbo and 2.4L GDI engines
- Certain 2014-2015 MY Tucson (LM) vehicles with Theta II 2.4L GDI engines
- Certain 2018-2019 MY Tucson (TL) vehicles with Theta II 2.4L GDI engines
- Certain 2019 MY Veloster N (JSN) vehicles with Theta II 2.0L Turbo GDI engines

Circulate To: General Manager, Service Manager, Parts Manager, Warranty Manager, Service Advisors, Technicians, Body Shop Manager, Fleet Repair