

SSM 50744 - 2013-2022 Various Hybrid Transmission Vehicles - HF35/HF45 Transmission – Lower Level Service Tools And Parts Now Available

Some 2013-2018 C-Max, 2013-2020 Fusion/MKZ, 2020-2022 Escape, 2021-2022 Corsair, 2022 Maverick vehicles equipped with HF35/HF45 hybrid transmissions can now be disassembled to repair and clean any contamination that may have been the result of a differential or transfer shaft bearing failure and the transmission can be overhauled/rebuilt. Service tools and service parts are now available. Refer to the Workshop Manual, Section 307-01.

APPLICABLE VEHICLES

2013 - 2018 CAR: CG C344N C-MAX
2013 - 2020 CAR: C7 CD391N FUSION
2013 - 2020 CAR: C7 CD391N FUSION
2013 - 2020 CAR: C9 CD533N MKZ
2013 - 2020 CAR: C9 CD533N MKZ
2020 - 2022 CAR: TC CX482N ESCAPE
2021 - 2022 CAR: TF CX483N CORSAIR
2022 CAR: FE P758N C-PICKUP