



SIB 61 05 22

2022-03-29

DELIVERY STOP: 12V BATTERY VENT TUBE

MODEL

E-Series	Model Description	Production Date
G05	X5 Sports Activity Vehicle	March 23, 2022

AFFECTED VEHICLES

Vehicles which require this Campaign to be completed will show it as "Open" when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System), ISPA Next or Warranty Vehicle Inquiry.

SITUATION

BMW AG has issued a Delivery Stop (effective March 29, 2022) on three (3) Model Year 2022 BMW X5 SAV vehicles that were produced on March 23, 2022. The 12V battery vent tube will need to be replaced.

Do not deliver to a customer, a New, Certified Pre-Owned or Used vehicle subject to a Delivery Stop, until the vehicle is repaired. Do not use or sell replacement equipment/parts subject to a Delivery Stop.

The bulletin will be updated when additional information becomes available.