

SSM 50786 - 2015-2020 F-150, 2017-2022 Super Duty And 2018-2021 Expedition - Driver Air BagCover Cracked/Splitting

Some 2015-2020 F-150, 2017-2022 Super Duty and 2018-2021 Expedition vehicles may experience a cracked or splitting driver air bag cover. This may be due to the air bag cover tear seam design. An updated driver air bag assembly has been released with a more robust air bag cover design. Refer to Workshop Manual (WSM), Section 501-20B for the replacement procedure. If servicing under warranty, use causal part 15043B13 for F-150 and Expedition or 25043B13 for Super Duty and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS)Manual.

APPLICABLE VEHICLES

2015 - 2020 TRUCK: FC P552N F-150

2018 - 2021 TRUCK: B8 U553N EXPEDITION

2017 - 2022 TRUCK: FE P558N SUPER DUTY