

SSM 50800 - 2020-2021 Explorer/Aviator - Illuminated Charge Warning Lamp With Diagnostic Trouble Code (DTC) B11D9

Some 2020-2022 Aviator/Explorer Hybrid vehicles may experience a low battery warning message displayed in the message center with diagnostic trouble code B11D9 present in the body control module (BCM). Refer to Workshop Manual, Section 414-01, Pinpoint Test C for diagnosis and repair. If the 125 amp fuse on the 14300 wire harness at the auxiliary battery is open, it is not necessary to replace a complete wire harness to obtain this fuse. Service part number JU5Z-14526-A is now available separately for service.

APPLICABLE VEHICLES

2020 - 2022 CAR: TV U611N AVIATOR
2020 - 2022 CAR: TW U625N EXPLORER