



STAR ONLINE PUBLICATION




Case Number: S2208000085

Release Date: March 2022

Symptom/Vehicle Issue: No Start, ABS Module Has No Communication, Stop/Start Inoperative

Customer Complaint /Technician Observation: Owner complaint, multiple warning lamps are on, vehicle will not start, Stop/Start Inoperative. Technician observed the vehicle is setting multiple U codes for communication and PCM DTC's. Associated DTC's U0121, P443, P057C, P06DA, B11FE-12, U110, U1120, U1141, U120C, U12A8.

Discussion: Inspect ground location G907A, clean and secure to complete, no parts required. Verify operation.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found