

## **Technical Service Bulletin**

Technical Service Bulletin: TSB220009 Released Date: 13-Jan-2022
Revised Minimum Reuse Spark Plug Gap: Inactive Misfire Fault Codes

# Revised Minimum Reuse Spark Plug Gap: Inactive Misfire Fault Codes

## Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

#### **Product Affected**

- ISX12 G CM2180 EJ
- ISX12N CM2380 X120B

#### **Description of Change**

The minimum reuse spark plug gap has been revised in Service Manual Procedure 013-016 in Section 13.

#### **Reason for Change**

#### Symptom:

- Rough running
- Fault Code(s): 5895, 5896, 5897, 5898, 5899, 5911, 5911, 5911, 6413, 6425, 6426, 6427, 6428, 6429, 6431

#### Root Cause:

Previous reuse spark plug gap resulted in no trouble found part replacements.

#### Verification

- Verify unit is running rough or experiencing any of the associated fault codes listed in the Symptom section above.
- See corresponding Service Manual for spark plug gap specification. Reference Procedure 013-016 in Section 13.

#### Resolution

- · Reuse spark plug gap minimum limit has been reduced.
- Verify the reuse spark plug gap is between the published limit specified. See corresponding Service Manual. Reference Procedure 013-016 in Section 13.
- Compare the engine control module (ECM) code and revision number in the ECM to the calibration revision listed in the ECM calibration revision history for applicable changes. If a calibration update for this fault code is available, the ECM calibration revision must be that revision or higher.

#### **Publications Affected**

Table 1, Publications Affected					
Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	
Service Manual	ISX12G CM2180 EJ	4310682	Spark Plugs (Non-Shielded)	Refer to Procedure 013- 016 (/qs3/pubsys2/x ml/en/procedure s/181/181-013- 016.html)	
Service Manual	ISX12N CM2380 X120B	5411406	Spark Plugs (Non-Shielded)	Refer to Procedure 013- 016 (/qs3/pubsys2/x ml/en/procedure s/525/525-013- 016.html)	

## **Document History**

Date	Details		
2022-1-13	Module Created		

Last Modified: 13-Jan-2022