

Reference SSM58937

XK / X150

Models XJ / X351

XF / X250

Title Cigar Lighter Elements Not Supplied

Category Electrical

Last modified 14-Sep-2012 00:00:00

Symptom 205000 Electrical Accessories

Issue:

No cigar lighter elements supplied at PDI.  
Blanking caps are supplied instead.

Cause:

Incorrect update to the Vista dealer ordering system from  
OXO chart feeds within manufacturing process.

Content

Action:

This is the correct condition introduced at the  
following VIN#s;

XK - B48817

XJ - V37934

XF - S20753