

Reference SSM63477

Models XK / X150  
XF / X250

Title Programming Issues for replacement KVM (8G9N-19G481-AB)

Category Diagnostic Software Hardware

Last modified 26-Feb-2013 00:00:00

Symptom 000101 Diagnostic Concerns

**Issue:**

Users have reported various problems programming replacement KVM on X150 & X250 vehicles.

**Cause:**

SDD is unable to correctly program a recent hardware change / parts supersession. Replacement components labelled 8G9N-19G481-AB are affected.

Content

**Solution:**

A permanent solution is scheduled for release on DVD133.03 near March 8<sup>th</sup> 2013

In the interim, before attempting any programming work using SDD on these specific modules, contact the Jaguar Technical Helpline for assistance. A manual patch is currently available for use as required.