

2015-2016 Mazda3 ***MIL ON WITH DTC P0451 AND/OR P013A***

Some customers may complain about a MIL ON with DTC P0451 (Fuel tank pressure sensor: sensor characteristic malfunction) and/or P013A (HO2S: Slow response (during transition from rich to lean)). Recall 8615J repair procedure may correct this concern.

Repair

1. Use eMDCS to check for open recalls.
2. Does Recall 8615J show OPEN?
 - Yes - Perform recall 8615J repair procedure.
 - No - This article does not apply. Proceed to normal Workshop Manual diagnosis.

An editorial board comprised of MNAO service staff members generates, collects, and verifies information for this publication. © 2015 Mazda Motor of America, Inc.

To contribute repair tip ideas, send an e-mail to mtips@mazdausa.com or fax to (949) 442-6599. If we select your repair tip, you will receive 10,000 Reward Performance by Mazda (RPM) points for your efforts. All contributions become property of MNAO, which assumes permission to publish them without further consideration.