



TECH TIP

**2022MY-2023MY L SERIES TRUCKS A/C
PERFORMANCE ISSUE**

**GROUP: 0-GENERAL
TECH TIP NO: TT-22-012
DATE: 5-12-2022
REF: HMM-220509-B1**

SUBJECT VEHICLES: Certain 2022-2023 Model Year L-Series Trucks Equipped with a Cummins Engine.

OVERVIEW

Customer reports poor or intermittent cooling from the air conditioning system.

Note: This Technical Tip is provided as technical information and is not authorization for a warrantable repair.

DESCRIPTION OF CONDITION

Some vehicles may have received a refrigerant overcharge during vehicle assembly. If a customer reports poor or intermittent cooling from the air conditioning system on a subject vehicle, first recover the refrigerant from the vehicle and recharge to 450 grams (1lb) of refrigerant. Test air conditioning system operation before performing any additional diagnostics or repairs.

