



(Back Office Only) Mack Chassis - Cruise Control Inoperative After Disabling The Electronic Stability Program (ESP)



> **Internal Content**

Confirm that:

1. Variant ESP-BAS1 is changed to UESP.
2. VECU parameter LEK is set to 0.



Tags

[mack](#)

[esp](#)

[bendix](#)

Related links and attachments

No links or attachments available



Feedback

[Give feedback](#)

to help improve the content of this article