



TECHNICAL SERVICE BULLETIN

Classification: BT21-012A	Reference: NTB21-069A	Date: April 29, 2022
------------------------------	--------------------------	-------------------------

ELECTRONIC SHIFTER ASSEMBLY

This bulletin has been amended. See AMENDMENT HISTORY.
Please discard previous versions of this bulletin.

APPLIED VEHICLES: 2021-2022 Rogue (T33)
2022 Pathfinder (R53)

APPLIED VINS: Rogue - 11th character of VIN is C
Pathfinder - All

SERVICE INFORMATION

If the customer has a concern of a MIL, and a DTC(s) is stored in any module,

AND

The ESM diagnosis of the DTC(s) leads to replacement of the electronic shifter assembly,

AND

It is determined that the electronic shifter assembly is inoperable due to an electrical or mechanical failure including any evidence of liquid intrusion directly into the electronic shifter assembly.

Submit a factory warranty claim for replacement of the electronic shifter assembly.

Do **NOT** charge the customer for replacement of the electronic shifter assembly.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
July 30, 2021	NTB21-069	Original bulletin published
April 29, 2022	NTB21-069A	Changes made throughout

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.