

<b>Subject</b> <b>4WD Inoperative, Lights Flashing on Dash</b>		<b>Market</b> <b>USA</b>
<b>Service Category</b> <b>Drivetrain</b>	<b>Section</b> <b>Transfer/4wd/Awd</b>	
<b>Applicability</b> <b>2018-2022 Tacoma</b>		

**APPLICABLE VEHICLES**

2018-2022

Tacoma

**CONDITION**

Water intrusion to the ADD actuator is currently being investigated as a cause of 4WD inoperative complaints. P17A0 and P17A4 DTCs may set for this condition but not always.

**RECOMMENDATIONS**

Please create a TAS case and contact TAS for instruction prior to diagnosing or repairing of the vehicle. If it is a weekend or a holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available workday.

**LINK REFERENCES**

This Tech Tip does not contain any link references