

Notification of UPS7513: Incorrect Rear Anti-Roll Bar

17-DEC-13 | No.: 6-215NAS | Section: GENERAL
INFORMATION | Market: CAN / USA

DESCRIPTION

A potential concern has been identified with a small number of 2014 model year Jaguar XJR vehicles. The affected vehicles have been manufactured with an incorrect rear anti-roll bar (17 mm bar fitted; should be 18 mm bar).

AFFECTED VEHICLES

The VIN range of affected vehicles is V51872-V63402.

ACTION TO BE TAKEN

Retailers must use DDW system vehicle inquiry screen to check for all affected vehicles within the VIN range that are in their control for 'K207' eligibility and refrain from releasing these vehicles for new or used vehicle sale until further instructions are provided.

SERVICE PROGRAM

Jaguar is currently in the process of developing a robust repair procedure. A further communication will be sent detailing the necessary action required for vehicles in retailer inventory.

Thank you for your cooperation in this matter. Jaguar apologizes for any inconvenience this may cause.