

SSM 50872 - 2020-2022 Aviator - Not Transitioning To Night Mode In Low Ambient Light Conditions

Some 2020-2022 Aviator vehicles may exhibit an issue transitioning to night mode in low ambient light conditions. This may be due to accessory protocol interface module (APIM) software. Inform customers that engineering is currently working on a solution for this condition and will be released via an over the air (OTA) software update expected in July 2023. Software will update automatically if the vehicle is connected to LincolnWay. Monitor OASIS for additional information. Schedule a service appointment for customers that are not connected to LincolnWay once the repair becomes available.

APPLICABLE VEHICLES
2020 - 2022 CAR: TV U611N AVIATOR