



Warranty Automated Manual Transmission (AMT, I-Shift, mDrive) Control Housing Assembly; Guidelines For Filing A Claim For Chassis Return Visit With Transmission Issues After A Repair Requiring Control Housing Removal And Reinstallation - US07 And N



> Internal Content

When reinstalling a Control Assembly onto an AMT following inspection or repairs, Guide Pins (Part Number 9996876) must be used to ensure proper orientation. An AMT main box with the guide pins properly installed can be seen below:



If Guide Pins are not used, misalignment of the Control Housing can cause damage to the tone ring as shown below:



Warranty Guidelines:



Accepted As Warranty:

- **Symptom:** Driveability issues / Transmission Fault codes
- **Cause:** If there is a defect in material and if the transmission is still under coverage a warranty claim may be submitted.
- **For further information:** Please refer to Impact Function group 431.



Not Accepted As Warranty:

- **Symptom:** Driveability issues / Transmission Fault codes
- **Cause:** It is the responsibility of the repairing dealer to follow published repair methods.
- **For further information:** Please refer to Impact Function group 431.



Tags

[k05792261](#)

[mack](#)

[volvo](#)

Related links and attachments

No links or attachments available



Feedback

[Give feedback](#)

to help improve the content of this article