




Volvo Chassis - Air Leak At Wet Tank - Model VNL



> **Internal Content**

Volvo VN models have been reported having the wet tank, located on the front (outside) side of the wet tank, air line rub the chassis fairing. If the truck was built starting March 11, 2019 with air tank 22945941 and air fittings 991083 or 991965, in the front port of the air tank, this issue is possible. To correct this issue, replace fittings 991083 or 991965 with fitting 20999390.

Refer to the pictures below.

Fitting - 20999390	Global Fitting - 991083 / 991965
	









Tags

[k52236323](#)

[vnl](#)

[volvo](#)

Related links and attachments

No links or attachments available



Feedback

[Give feedback](#)

to help improve the content of this article