

## Traffic light view intermittently inoperable after performing a software update of the MBUX Multimedia System (A26/17)

---

Topic number	LI82.85-P-075094
Version	1
Function group	82.85 - Navigation and Communication systems
Date	7/19/22
Validity	Model Series 206, 223, 232, and 297 with code U19
Reason for change	

---

### Complaint

Traffic Light View is intermittently inoperable after updating the MBUX Multimedia System (A26/17) to E316.5.

### Cause

Currently available MBUX software release

### Remedy

A software remedy is currently being developed.

Note: Do not replace any parts for this complaint.

Symptoms				
Communication/information > Assistance and warning systems > Augmented reality camera > Malfunction				
Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note