Reference	SSM75802
Models	New Range Rover / L460 New Range Rover Sport / L461
Title	Deployable Side Step - No operation
Category	Accessories
Last modified	25-Jul-2022 00:00:00
Symptom	Electrical Accessories
Content	Issue: Customer states that the deployable side steps are not operational. Cause: This has occurred after CCF As-Built has been loaded into the vehicle. Loading the CCF as-built has removed the Deployable Side Step option from the CCF.
	A . 13

Action:

Please follow step 8 completely in the accessory fitting instructions for Deployable Side Steps (Electrical Only) only after all other CCF work has been completed.