

10/16/15

MY15 RT

## GPOP - Issue Review System

**Part Number:** L0003757\$\$

**Part Description:** Turn Signal Bulb

---

**Issue Description:** If the filament is broken proceed as normal following the parts return process. If the filament is not broken and does not function follow the process listed in this bulletin. If the customer complaint is (bulb inoperative) please change the bulb L003757NAK and socket P/N 68030801AA and return together to the Quality Engineering Center (QEC) for analysis. It is very important to have both bulb and socket together for traceability. Email the last 8 of the VIN, mileage and send the part to the QEC.

Contact Bill Egglezos- cell (248) 821-5332 bill.egglezos@fcagroup.com, if you have further questions.

~  
Contact Us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

---