



TECH TIP

**TT-22-017 L-SERIES DIAGNOSTIC TROUBLE
CODE (DTC) 0559 TECH TIP**

**GROUP: 0-GENERAL
TECH TIP NO: TT-22-017
DATE: 9-23-2022**

Subject Vehicles: 22MY-23MY L-Series trucks equipped with an Cummins engine, with a check engine light on and has a DTC 0559.

Note: This Technical Tip is provided as technical information and is not authorization for a warrantable repair.

OVERVIEW:

If a Cummins equipped Hino L-series arrives with a check engine light or fuel system related concern setting Cummins DTC 0559, please open a Hino TechAssist case for further direction. When opening the Hino TechAssist case, be sure to include an ECU image from the Cummins ECU and the exact symptom(s) the customer is experiencing for additional assistance.

