


Subject <b>2018-2022 Tacoma/4Runner Transfer Case Leak</b>		Market <b>USA</b>
Service Category <b>Drivetrain</b>	Section <b>Transfer/4wd/AwdAwd</b>	
Applicability <b>2018-2022 Tacoma/4Runner</b>		

**APPLICABLE VEHICLES**

2018-2022	Tacoma	2018-2022	4Runner
-----------	--------	-----------	---------

**CONDITION**

This condition is currently under investigation. Oil may be found leaking from the transfer case input or rear output shaft seal as seen in the example pictures below:



*Figure 1 Rear Output Shaft Seal Leak*



*Figure 2 Input Shaft Seal Leak*

**RECOMMENDATIONS**

If you see this condition, please create a TAS case and contact TAS for instruction prior to diagnosing or repairing of the vehicle. If it is a weekend or holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available workday.

**LINK REFERENCES**

This Tech Tip does not contain any link references