

9003764 08/02/2017 MY16, 17 DS

## **GPOP - Issue Review System**

**Part Number:** 68197370A\$

**Part Description:** Brake Booster

---

**Issue Description:** If replacing booster for squeak, click, or pop noise when applying brake pedal, please attempt greasing interface between brake pedal pin and brake booster eyelet.  
Use a general all-purpose grease such as MS-4178 used on steering linkages.

~\_\_\_\_\_  
Contact us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

---